

DIPS/Uggi/1754

PART - I  
PERFORMA FOR THE SAFETY OF SCHOOL BUILDING

(To be filled by the Head of school/ Institution)

- 1 (a) Name of the school DIPS School
- (b) Level/Standard of School: .....
- Whether School is affiliated to C.B.S.E. or P.S.E.B. If affiliated then affiliation No. .....
- 2 Location VPO = UGGI, MODEL TOWN, TEHSIL NAKODAR
- 3 Plot Area 43415 sq. Ft (4323.89 sq. yd)
- 4 Plinth Area 46194 sq. Ft
- 5 Number of Storey Two
- 6 Year of construction of building. 2014
- 7 If the building has been constructed under the Supervision of the Qualified Engineer, the following details may be given.
- Mr. Sachin Gandhi  
Constructed under Self Supervision
- B.E. (Civil)  
191, Gyanal Nagar, Jalandhar
- a) Name of the Engineer with Qualification Mr. Sachin Gandhi BE (Civil)
- b) Address of the Engineer 191, Gyanal Nagar, Jalandhar
- c) Detail of structural drawings used in the construction. .....
- d) Name & Address of Architect with qualification. Mr. Rajnish CB Arch)
- 8 Whether the building has been constructed for the purpose of
- a) School Yes
- b) Residential purpose and converted for use as a school: NO
- 9 Material used for roofs
- a) R.C.C. slabs Yes
- b) R.S Joists & Battens NO
- c) Wooden Joists & Battens. NO
- 10 Material used for walls
- a) Mud mortar NO
- b) Cement mortar Yes
- c) Plaster i) Lime mortar .....  
ii) Cement mortar .....
- 11 Flooring :-
- a) Conglomerate Yes
- b) Terrazo Yes
- c) Brick paving NO
- 12 A detailed drawing indicating dimensions of the rooms alongwith size and location of doors and windows. Detail drawing attached. Detail Attached
- 13 Whether fire safety certificate obtained from concerned fire officer. Yes

It is also certified that there is no any court case or stay is pending regarding this building in any Hon'ble Court.

Signature and Stamp of the Head

Principal  
DIPS School Uggi  
Affiliated with

PART - II

SCHOOL BUILDING SAFETY CERTIFICATE

(TO BE FILLED BY THE S.D.E OF P.W.D. B&R DEPARTMENT)


Name of the School: D.P.S. School, Uggai Tehsil,  
Nehrodah, Distt. Jalandhar

- 1) This office Assistant Engineer/Junior Engineer visited the above mentioned School on... 06.14.2021 and have visually inspected it for its safety and find it fit for normal use as a school building.
- 2) In case any addition or expansion and modification to this building is to be carried out same may be done under the supervision of a technically qualified Engineer and this certificate may again be obtained after the completion from the undersigned.
- 3) In case the building is effected by flood, or if there is settlement of walls/ foundation or sagging of roofs etc. immediately inspection of the undersigned be arranged to check the stability and the safety of the building.
- 4) This building is found visually safe hence it is expected that it can be safely occupied for normal use up to (Indicate year upto which it can be used)

1-4-2021 to 31-3-2022 (~~For~~ Under Normal conditions)

Ref. No. 195

Dated 10/4/2021

  
Executive Engineer  
Construction Division No. 1,  
PWD B&R Br., Jalandhar Cantt.  
